Dry Contact I/O Card (AP9614) Firmware v3.1.4.1 Release Notes

Table of Contents

Affected Revision Levels	1
New Features	1
Fixed Issues	
Known Issues	
Hash Signatures	
idon Orginitario	2

Affected Revision Levels

Top ↑

Component	File	Details
Dry Contact I/O Card Application	apc_hw21_relayio_3-1-4-1.nmc3	Application for Dry Contact I/O SmartSlot Card (AP9614)

For details on upgrading the firmware for the Dry Contact I/O SmartSlot Card (AP9614), see the **Installation** and Configuration guide.

New Features

Top ↑

New Feature

There is no new feature in this release.

Fixed Issues

Top ↑

Fixed Issue

UPS models now display correct information for the AP9614 card in the **About > Accessory** screen.

Security Update

The following security vulnerability has been addressed in this release:

 CWE-307: Improper Restriction of Excessive Authentication Attempts. This software does not implement sufficient measures to prevent multiple failed authentication attempts within a short time frame, making it more susceptible to brute force attacks.

The account now gets locked after bad login attempts.

Fixed Issue

The following security vulnerability has been addressed in this release:

• CWE-79: Improper neutralization of input during web page generation (Cross-site Scripting)

Known Issues

Top ↑

Known Issue

The Web UI access to AP9614 disconnects occasionally with a display message "site can't be reached". This requires the USB cable to be unplugged and reconnected.

In some older UPSs, overload isn't treated as a fault by AP9614, which leads to legacy faults ignoring the overload condition.

Hash Signatures

Signatures	apc_hw21_relayio_3-1-4-1.nmc3	
CRC32	1228C0FC	
CRC64	119909C96A3FF2D5	
SHA-256	2F7AD2712438114976D0910E4B51DF4AF380F79FF34293E4E270D1BBCA94EE0F	
SHA-1 2809FE60DAC3A3A156EBA33F9BD891B9786C4189		
BLAKE2sp	21DE7E4B3B39059DEA77352481BB24872C567EC7646F86B729F7A1DC8D3F203E	

Copyright © 2025 Schneider Electric. All rights reserved.

https://www.se.com

TME76693A

05-2025