



# USB-C Triple-Monitor Dock - HDMI or DP, 4x USB-A/3x USB-C, 2.5GbE, 140W PD

## **Product ID**


DK30C2DPEPRN DK30C2DPEPRUE

## **Front View**





## **Rear View**



Component		Function
1	USB-A Data Port	<ul><li>Connect a USB Peripheral</li><li>Supports USB 5Gbps</li></ul>
2	USB-A Data/Charge Port	<ul> <li>Connect and/or charge a USB Peripheral</li> <li>Supports USB 5Gbps and 7.5W BC 1.2 Charging (5V/1.5A)</li> </ul>
3	USB-C 5Gbps Port	<ul> <li>Connect and/or charge a USB Peripheral</li> <li>Supports USB 5Gbps and USB Power Delivery 3.0 up to 18W</li> </ul>
4	Headset Port	Connect a 3.5mm Headset
5	Power Button	Press and release to toggle power on or off for the <b>Docking Station</b>
6	3x Lock Slots (Nano/Standard/Wedge)	Connect a K-Slot, Nano, or Wedge Style Locking Device to deter theft of the Docking Station
7	2.5 Gigabit Ethernet Port	<ul> <li>Connect the <b>Docking Station</b> to a <b>Network</b></li> <li>Supports <b>2.5GBASE-T</b></li> </ul>
8	Video Output 1	Connect to an HDMI or DisplayPort Display
9	Video Output 2	Connect to an HDMI or DisplayPort Display
10	USB 2.0 Ports	<ul> <li>Connect a USB Peripheral (Mouse/Keyboard)</li> <li>Supports USB 480Mbps</li> </ul>
11	USB-C 10Gbps Port	<ul><li>Connect a USB Peripheral</li><li>Supports USB 10Gbps</li></ul>
12	USB-C Video/Data Port	<ul> <li>Connect a USB Peripheral or an External Display</li> <li>Supports DP Alt Mode and USB 10Gbps</li> </ul>
13	USB-C Host Connection	<ul> <li>Connect to a USB-C Port on the Host Computer</li> <li>Supports Power Delivery 3.1 for up to 140W Laptop Charging</li> </ul>
14	Power Input	Connect the <b>Docking Station</b> to a <b>Power Source</b> using the included <b>Universal Power Adapter</b>

# **Package Contents**

- Docking Station x 1
- 3ft (1m) USB-C Host Cable x 1
- Universal Power Adapter x 1
- Power Cable x 1
- Quick-Start Guide x 1

# Requirements

For the latest manuals, product information, technical specifications, and declarations of conformance, please visit: <a href="https://www.StarTech.com/DK30C2DPEPRN">www.StarTech.com/DK30C2DPEPRN</a> <a href="https://www.StarTech.com/DK30C2DPEPRUE">www.StarTech.com/DK30C2DPEPRUE</a>

- Computer x 1
  - USB-C port with DP Alt Mode and Power Delivery support
  - Video performance, such as resolution and refresh rate, depends on your host computer's video controller. Please verify your computer's specifications

## Installation

- 1. Connect the Power Adapter from an AC Outlet, to the DC 20V Port on the Docking Station.
- 2. Connect a Mouse, Keyboard, or other USB 2.0 Devices to the USB 2.0 Ports on the back of the Docking Station.
- 3. Connect a USB Device to the USB-C 10Gbps Port on the back of the Docking Station.
- 4. Connect a USB Device to the USB-A Data/Charge Port on the front of the Docking Station.
- 5. Connect a USB Device to the USB-A Data Ports on the front of the Docking Station.
- 6. Connect a USB Device to the USB-C 5Gbps Port on the front of the Docking Station.
- 7. Connect a 3.5mm Headset to the 3.5mm Headset Port on the front of the Docking Station.
- Connect a Network Cable from a Network Port/Device to the 2.5 Gigabit Ethernet Port on the back of the Docking Station.

### 9. Video Output 1

Connect an **HDMI Cable** (sold separately) from the **HDMI Display**, to the **HDMI Output Port** on the **Docking Station**.

Connect a **DisplayPort Cable** (sold separately) from the **DisplayPort Display**, to the **DisplayPort Output Port** on the **Docking Station**.

## 10. Video Output 2

Connect an **HDMI Cable** (sold separately) from the **HDMI Display**, to the **HDMI Output Port** on the **Docking Station**.

Connect a **DisplayPort Cable** (sold separately) from the **DisplayPort DisplayPort Output Port** on the **Docking Station**.

## 11. USB-C Video/Data Port

Connect a **USB-C Cable** or **Video Adapter** (sold separately) from the **USB-C Video/Data Port** on the **Docking Station** to a **Display**.

or

Connect a USB Device to the USB-C Video/Data Port on the Docking Station.

- 12. (Optional) Connect a **K-Style**, **Nano**, or **Wedge Laptop Lock** (sold separately) to the corresponding **Lock Slot** on the side of the **Docking Station**.
- 13. Connect the included **3ft (1m) USB-C Host Cable** from the **USB-C Host Connection** on the back of the **Docking Station** to a **USB-C Port** on the **Laptop**.

Note: For full functionality, the Laptop's USB-C Port must support Power Delivery and DP Alt Mode.

- 14. Press the **Power Button** on the front of the **Docking Station** to power on the **Dock**.
- 15. The Host Computer will automatically detect the Docking Station and install the required Drivers.
- 16. (Optional) If the **Drivers** do not automatically install, disconnect the **Docking Station** from the **Computer**, then:
  - a. Navigate to <a href="https://www.StarTech.com/DK30C2DPEPRN">www.StarTech.com/DK30C2DPEPRUE</a>, and click the <a href="https://www.StarTech.com/DK30C2DPEPRUE">Drivers/Downloads</a> tab.
  - b.Under **Driver(s)**, download the **Driver Package** for your operating system, and follow the steps outlined in the **Installation Guide**, that's included in the **Driver Package**.

#### Notes

- The docking station housing meets enclosure fire requirements, providing enhanced protection through compliant structural design.
- This equipment complies with European Commission Regulation (EU) 2023/826; the Off-Mode power consumption is less than 0.3W.
- This equipment is only suitable for mounting at heights  $\leq 2m$ .
- The product marking and identification label are located on the bottom of the device.

